

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2025

Submitted Date:

11/18/2025

Document Number:

719500642

**FIELD INSPECTION FORM**

Loc ID 312392 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 29470  
Name of Operator: FEES JR AND SON OIL & GAS\* WALTER S  
Address: 2516 FORESIGHT CIRCLE RM #10  
City: GRAND JUNCTION State: CO Zip: 81505

**Findings:**

- 16 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fees, Walter		fwalter8@bresnan.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119430	PIT	AC	08/27/2014		-	GIPSON 28-3	AC
221470	WELL	SI	08/01/2025	GW	077-08071	BAR-X 28-3	SI

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 11/6/2025 at approximately 15:05, Compliance Inspector Matthew Morris conducted an on-site audit at FEES JR AND SON OIL & GAS\* WALTER S, BAR-X-68S104W/28SESW at Location ID #312392 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign posted.		
Corrective Action:	Install battery sign to comply with CECMC rules.	Date:	12/19/2025
Type	TANK LABELS/PLACARDS		
Comment:	No labeling on storage tanks.		
Corrective Action:	Install labels to comply with CECMC rules.	Date:	12/19/2025

<b>Emergency Contact Number:</b>			
Comment:	911/(970)242-2044		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Stored/unused equipment on location.		
Corrective Action:	Remove stored/unused equipment from location.	Date:	11/26/2025
Type	WEEDS		
Comment:	Weeds across location.		
Corrective Action:	Remove weeds from location.	Date:	11/26/2025

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Livestock fencing around compressor		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock fencing		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:	Wildlife entry hazard on separator.		
Corrective Action:	Secure equipment to prevent wildlife entry.		Date: 11/24/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1	100 BBLS	STEEL AST		,	
Comment:	No label on tank to identify contents.					
Corrective Action:						Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Weeds present in secondary containment.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1	300 BBLS	STEEL AST		,	
Comment:	No label on tank to identify contents.					
Corrective Action:						Date:

**Paint**

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Weeds present in secondary containment.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 119430 Type: PIT API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 221470 Type: WELL API Number: 077-08071 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last produced July 2025 per production report.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Compaction						
		Compaction				
		Ditches				
		Gravel				
Berms						
Gravel						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: NO Pit ID: 119430 Lat: 39.334064 Long: -108.997304

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
During the audit, the following compliance issues were observed:  1) No battery sign 2) No labels on storage tanks 3) Weeds present across location 4) Stored/unused equipment on location 5) Wildlife entry hazard at separator	morrism	11/18/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404441120	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7337869">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7337869</a>
719500643	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7337811">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7337811</a>