

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2025

Submitted Date:

11/25/2025

Document Number:

716301764

FIELD INSPECTION FORM

Loc ID 309391 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
B WARD, GIENA		gward@ogrisop.com	All Inspections
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294300	WELL	PR	07/01/2023	CBM	071-09474	NEW ELK 25-02	PR
296581	PIT	AC	09/08/2008		-	NEW ELK 25-02	AC

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.		Date:
Type	WEEDS		
Comment:	PHOTO 4: WEEDS NOT MAINTAINED NEAR WELLHEAD AND METER HOUSE.		
Corrective Action:	MAINTAIN WEEDS PER FULE 606.		Date: 12/08/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#		corrective date
Type: Other		# 1		
Comment:	ABOVE GROUND 25 BBL PRODUCED WATER/ USED OIL TANK.			
Corrective Action:				Date:
Type: Prime Mover		# 1		
Comment:				
Corrective Action:				Date:
Type: Progressive Cavity		# 1		
Comment:				
Corrective Action:				Date:
Type: Compressor		# 1		
Comment:	FORM 4 SUNDRY IS ON FILE (VACUUM)			
Corrective Action:				Date:
Type: Bradenhead		# 1		
Comment:	IS ACCESSABLE			
Corrective Action:				Date:
Type: Gas Meter Run		# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:				Date:

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 294300 Type: WELL API Number: 071-09474 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296581 Type: PIT API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Sediment Traps	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment: PHOTO 6 & 7: OILY WASTE IN COMPRESSOR SKID.

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO DRAIN OILY WASTE, 10 DAYS TO REPAIR LEAKING EQUIPMENT.

Date: 01/08/2026

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 296581 Lat: 37.148160 Long: -104.944400

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____
 Corrective _____ Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____
 Corrective _____ Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____
 Corrective _____ Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____
 Corrective _____ Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	296581	2017102	
	296581	2017102	

ECMC Comments

Comment	User	Date
<p>THIS IS A FOLLOW-UP TO INSP. DOC #698707766, CA HAS NOT BEEN SAFISFACTORILY ADDRESSED AND THERE ARE NEW CA'S.</p> <p>ECMC Inspection Report Summary On Tuesday 11-25-2025 at approximately 14:45, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location NEW ELK 25-02 API# 05-071-0 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: WEED MAINTENANCE, RULE 606, CA DATE 12-8-2025. IMPACTED SOIL, RULE 1002.,(2).D. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED. OILY WASTE IN COMPRESSOR SKID, RULE1002..(2).D & 1002.f.(2)B, 24 HOURS TO DRAIN OILY WASTE 10 DAYS TO REPAIR LEAKS. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	11/25/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301765	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7349158