

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Energy and Carbon Management Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>11/24/2025</u> Submitted Date: <u>11/25/2025</u> Document Number: <u>719000988</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID 333934 Inspector Name: GARCIA, CHARLES On-Site Inspection   
 2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10133  
 Name of Operator: HILCORP ENERGY COMPANY  
 Address: P O BOX 61229  
 City: HOUSTON State: TX Zip: 77208

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258202	WELL	PR	12/01/2010	CBM	067-08335	SQUIRES 2	PR
301405	WELL	PR	11/16/2009	CBM	067-09702	SQUIRES 3	PR

**General Comment:**

[Inspection Report Summary](#)  
 On 11/24/25 I Inspector Charles Garcia conducted an desktop inspection.  
 Location: SQUIRES #3,#2  
 API# 067-09702 API# 067-08335  
 Operator: HILLCORP ENERGY COMPANY  
 County: LaPlata  
 DOC#719000852 FIR# RSOLUTION DOC #404440827 FIR PHOTOS DOC #404440839

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Other	# 2			
Comment:	WELLHEAD ON THE SQUIRES #3 HAD LEAK ON STUFFING BOX APROX 3 BBLs PRODUCED WATER SPILLED ONTO LOCATION MEASUREMENTS 50 FT LONG 12 FT WIDE 5IN INTO SOIL SEE LOCATION PICTURES CONTROL SPILL AND CLEAN UP FREE FLUIDS WITHIN 24 HRS SUBMIT FORM 19 WITHIN 24 HRS AND CONTACT JASON KOSOLA WITHIN 72 HOURS PER RULE 906 CA RESOLVED SEE LOCATION PICTURES FIR DOC#404440839 FIR RESOLUTION SUBMITTED			
Corrective Action:				Date: <input type="text"/>

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date: <input type="text"/>

**Flaring:**

Type			
Comment:			
Corrective Action:			Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 258202 Type: WELL API Number: 067-08335 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**BradenHead**

Date of Last Brhd Test: 06/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301405 Type: WELL API Number: 067-09702 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**BradenHead**

Date of Last Brhd Test: 06/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12