

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2025

Submitted Date:

11/25/2025

Document Number:

719700299

FIELD INSPECTION FORM

Loc ID 306191 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286285	WELL	PR	05/01/2020	OW	123-24168	CORNISH 14-8	PA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume			corrective date
Type: Emission Control Device	# 0				
Comment:	Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:
Type: Ancillary equipment	# 0				
Comment:	Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:
Type: Plunger Lift	# 0				
Comment:	Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 0				
Comment:	Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:
Type: Gas Meter Run	# 0				
Comment:	Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0					
Comment: Plugged & Abandoned PA. Equipment removed.						
Corrective Action:				Date:		

Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		

Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	

Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 286285 Type: WELL API Number: 123-24168 Status: PR Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 11/25/2025 at approximately 12:56 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: PDC ENERGY INC Location Name: CORNISH-66N63W/8SWSW Location ID: 306191 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.493840 / -104.470120</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 09/08/2025. Approval Pending. Plugged & Abandoned PA well GPS coordinates: 40.495190 / -104.467970 Form 27 on file. Approved.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	11/25/2025
<p>This is a PLUGGED & ABANDONED WELL audit. Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.493840 / -104.470120</p>	evinsb	11/25/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700300	Audit photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7349501