

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2025

Submitted Date:

11/19/2025

Document Number:

719000966

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
306775 \_\_\_\_\_ GARCIA, CHARLES \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10663  
Name of Operator: ENDURING RESOURCES LLC  
Address: 6300 S SYRACUSE WAY, SUITE 525  
City: CENTENNIAL State: CO Zip: 80111

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Walter, Klye		kwalter@enduringresources.com	<a href="#">SJB inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	<a href="#">SJB inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264033	WELL	PR	05/28/2002	CBM	067-08734	WEST ANIMAS-CARTER 7U-4 7U - 4	PR
476954	Domestic Tap	AC	07/11/2022		-	Domestic Tap 7NENE	AC

**General Comment:**

[Inspection Report Summary](#)  
On 11/19/25 I Inspector Charles Garcia conducted an on-site inspection.  
Location: WEST ANIMAS-CRATER 7U-4  
Operator: ENDURING RESOURCES  
API#: 067-08734  
County: LaPlata

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	ENTERANCE TO LOCATION HAS STORM WATER WASHOUTS ON BOTH SIDES OF ACCESS ROAD APPROXIMATELY 1/2 FT DEEP AND 2 FT WIDE IN SPOTS SEE LOCATION PICTIRES		
Corrective Action:	Stormwater management Erosion Control Install or repair required BMPs per Rule 1002.f.(2)C	Date:	12/03/2025

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	1-800-916-7897 911 EMERGENCY		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	6FT CHAINLINK		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404443601	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7340573">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7340573</a>
719000969	LOCATION PICTURES	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7340570">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7340570</a>