

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/12/2025

Submitted Date:

11/21/2025

Document Number:

701104341

FIELD INSPECTION FORM

Loc ID 334397 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295823	WELL	PR	08/31/2008	GW	045-15816	WRIGHT, SMALLWOOD, CASTEEL SG 34-28	EG
295824	WELL	PR	08/31/2008	GW	045-15817	WRIGHT, SMALLWOOD, CASTEEL SG 324-28	EG
295825	WELL	PR	08/31/2008	GW	045-15818	WRIGHT, SMALLWOOD, CASTEEL SG 344-28	EG
415912	WELL	PR	02/16/2011	GW	045-19171	WRIGHT, CASTEEL AND SMALLWOOD SG 341-33	EG
415915	WELL	PR	01/30/2011	GW	045-19173	WRIGHT, CASTEEL AND SMALLWOOD SG 544-28	EG
415920	WELL	PR	02/16/2011	GW	045-19176	WRIGHT, CASTEEL AND SMALLWOOD SG 443-28	EG
415922	WELL	PR	02/16/2011	GW	045-19177	WRIGHT, CASTEEL AND SMALLWOOD SG 24-28	EG
415931	WELL	PR	12/01/2010	GW	045-19180	WRIGHT, CASTEEL AND SMALLWOOD SG 31-33	EG
415933	WELL	PR	02/16/2011	GW	045-19181	WRIGHT, CASTEEL AND SMALLWOOD SG 331-33	EG
415942	WELL	PR	02/16/2011	GW	045-19183	WRIGHT, CASTEEL AND SMALLWOOD SG 434-28	EG
415953	WELL	PR	02/16/2011	GW	045-19188	WRIGHT, CASTEEL AND SMALLWOOD SG 533-28	EG
415956	WELL	PR	02/16/2011	GW	045-19189	WRIGHT, CASTEEL AND SMALLWOOD SG 424-28	EG
415963	WELL	PR	02/16/2011	GW	045-19193	WRIGHT, CASTEEL AND SMALLWOOD SG 431-33	EG

415965	WELL	PR	02/16/2011	GW	045-19194	WRIGHT, CASTEEL AND SMALLWOOD SG 433-28	EG
415966	WELL	PR	02/16/2011	GW	045-19195	WRIGHT, CASTEEL AND SMALLWOOD SG 543-28	EG
415970	WELL	PR	01/30/2011	GW	045-19197	WRIGHT, CASTEEL AND SMALLWOOD SG 334-28	EG
415974	WELL	PR	02/16/2011	GW	045-19198	WRIGHT, CASTEEL AND SMALLWOOD SG 44-28	EG
415977	WELL	PR	02/16/2011	GW	045-19200	WRIGHT, CASTEEL AND SMALLWOOD SG 41-33	EG
415978	WELL	PR	02/16/2011	GW	045-19201	WRIGHT, CASTEEL AND SMALLWOOD SG 444-28	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
 Tank labels are peeling.
 Install sign to comply with Rule 605.h.
 CA Date 12/24/2025

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Tank labels are peeling.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/24/2025
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	295823	Type:	WELL	API Number:	045-15816	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	295824	Type:	WELL	API Number:	045-15817	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	295825	Type:	WELL	API Number:	045-15818	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415912	Type:	WELL	API Number:	045-19171	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415915	Type:	WELL	API Number:	045-19173	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415920	Type:	WELL	API Number:	045-19176	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415922	Type:	WELL	API Number:	045-19177	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415931	Type:	WELL	API Number:	045-19180	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415933	Type:	WELL	API Number:	045-19181	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415942	Type:	WELL	API Number:	045-19183	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415953	Type:	WELL	API Number:	045-19188	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415956	Type:	WELL	API Number:	045-19189	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415963	Type:	WELL	API Number:	045-19193	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415965	Type:	WELL	API Number:	045-19194	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415966	Type:	WELL	API Number:	045-19195	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415970	Type:	WELL	API Number:	045-19197	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Facility ID: 415974 Type: WELL API Number: 045-19198 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415977 Type: WELL API Number: 045-19200 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415978 Type: WELL API Number: 045-19201 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404447362	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7344331
701104342	Flowline integrity inspection 701104341 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7344325