

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/28/2025</u> Submitted Date: <u>11/17/2025</u> Document Number: <u>712300257</u>
FIELD INSPECTION FORM			

Loc ID: 437712 Inspector Name: Maxwell, Logan On-Site Inspection:
 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
 4 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10396
 Name of Operator: SWN PRODUCTION COMPANY LLC
 Address: P.O. BOX 12359
 City: SPRING State: TX Zip: 77391-

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		swnsandwash@swn.com	All Inspections
		steve.freese@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437712	LOCATION	CL			-	NORTH HAYDEN 1-26	RI
437726	WELL	PA	10/24/2017	GW	107-06263	North Hayden 1-26	RI
443135	WELL	AL	05/18/2018	LO	107-06265	NORTH HAYDEN 7-88 2-26H	RI

General Comment:

On 10/29/2025, Northwest Reclamation Specialist Maxwell conducted a final reclamation inspection at SWN Production Company's North Hayden 1-26 Location in Routt County, Colorado.

Well 107-06263 was PA'd 10/24/2017 (Document No. 401499747). Flowlines abandoned 10/30/2017 (Doc No. 401857953). Well 107-06265 was AL'd 5/18/2018 (Document No. 401646017).

The Location is on State Land Board Surface and is in black bear habitat. In addition, the Location is in the following HPH: Rule 1202.c. NSO for Columbian Sharp Tailed Grouse Lek site; rule 1202.d. density for: Columbian Sharp Tailed Grouse production area, Elk Migration corridor, Elk Production Corridor, Elk Winter Concentration area, Greater Sage grouse priority habitat management and Mule Deer Migration Corridor; Rule 309.e.1. for Columbian Sharp Tailed Grouse Winter Range.


This inspection is in response to Form 4, Doc No. 403788003 (5/30/2024, stating Final Reclamation ready for Inspection) and a follow-up to Inspection #702800548.

The following compliance issues were observed in this inspection:
 -Weed Management
 -Final Reclamation
 -Stormwater Management

Refer to the "Location," "Reclamation," and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective actions from previous inspections that have not been addressed remain applicable. Any new corrective actions without corrective action dates, requires that the Operator comply with the Rules as soon as possible or when environmental conditions permit. Location will remain out of compliance until corrective action(s) has (have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.



Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment:

It was observed that debris, such as erosion matting, t-posts, etc., were left on the Location.

Corrective Action:

Comply with Rule 606. Remove all debris/trash.

Date:

Type

WEEDS

Comment:

It was observed in this inspection that undesirable plant species and Noxious weeds, including but not limited to Houndstongue, Canada Thistle, field pennycress, Musk Thistle had established on the access road and Location. Weeds shall be controlled during appropriate environmental conditions and timing.

Corrective Action:

Comply with Rule 606.c.

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 437712 Type: LOCATION API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437726 Type: WELL API Number: 107-06263 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443135 Type: WELL API Number: 107-06265 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed **Fail** No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present **Fail** Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

	<p>This location does not meet reclamation requirements. Perennial cover is not uniform and does not reach 80% of the reference area vegetation. There are areas throughout the Location and access road that have weeds or remain bare. Refer to the "Location" section of this inspection report for weed control corrective action. Other dominant vegetation observed on the Location included Crested wheatgrass, Western wheatgrass, Great Basin Wildrye, Artemisia ludoviciana, and rabbitbrush. Reference area vegetation includes Big sagebrush, western yarrow, western wheatgrass, Oregon grape, and aster forbs.</p>	
Corrective Action:	<p>Conduct additional reclamation in accordance with Rules 1004.d. and 1004.e. series rules. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels.</p>	Date _____
<p>Overall Final Reclamation Fail Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/></p>		

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Gully erosion is occurring in areas of poor vegetation establishment/bare ground in the eastern central areas of the Location. Long term stabilization of the Location is necessary for a passing final inspection.

Corrective Action: Comply with Rule 1002.f. Stabilize area with vegetation and/or properly install erosion control measures.

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404449391	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7347225
712300258	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7347224