

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2025

Submitted Date:

12/02/2025

Document Number:

701104360

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
335295 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 96850 _____
Name of Operator: TEP ROCKY MOUNTAIN LLC _____
Address: 1058 COUNTY ROAD 215 _____
City: _____ PARACHUTE _____ State: _____ CO _____ Zip: _____ 81635 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 _____ Number of Comments
- 2 _____ Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211334	WELL	PR	09/07/1997	GW	045-07094	RMV 65-20	EG
260690	WELL	PR	06/10/2002	GW	045-07901	CLOUGH RWF 534-20	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
1 broken releif cap flapper on 1" risers in front of RMV 210-20 separator.
Replace or repair flapper. CA Date 1/2/2026
Tank label is weathering and discolored.
Replace label. CA Date 1/2/2026

Location

Lease Road:

Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank label is weathering and discolored.		
Corrective Action:	Replace label.		Date: 01/02/2026

Emergency Contact Number:

Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume			
In Containment: No					
Comment: _____					
<input type="checkbox"/> Multiple Spills and Releases?					

Equipment:

			corrective date
Type:	Horizontal Heated Separator # 4		
Comment:	1 broken relief cap flapper on 1" risers in front of RMV 210-20 separator.		
Corrective Action:	Replace or repair flapper.		Date: 01/02/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		
Comment:	Label is discolored				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 211334 Type: WELL API Number: 045-07094 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 260690 Type: WELL API Number: 045-07901 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104361	Flowline integrity inspection 701104360 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355444