

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2025

Submitted Date:

12/02/2025

Document Number:

715203515

**FIELD INSPECTION FORM**

Loc ID 304744 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| Dolezal, Pat |       | pat.dolezal@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 273992      | WELL | PR     | 01/28/2005  | GW         | 125-08936 | SHAY 41-8     | PR          |

**General Comment:**

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

| <b>Location</b>  |  |        |                  |
|--|--|--------|------------------|
| <b>Lease Road:</b>                                     |  |        |                  |
| Type   | Access   |        |                  |
| comment:   | Trail through farm ground, CRP and pasture   |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                  |
| <b>Signs/Marker:</b>                                   |  |        |                  |
| Type   | WELLHEAD   |        |                  |
| Comment:   | Lease sign by water tank. Update to current operator   |        |                  |
| Corrective Action:                                     | Install sign to comply with Rule 605.d.  |        | Date: 01/01/2026 |
| Type   | TANK LABELS/PLACARDS   |        |                  |
| Comment:   | Metal sign by water tank. Update to current operator   |        |                  |
| Corrective Action:                                     | Install sign to comply with Rule 605.h.  |        | Date: 01/01/2026 |
| Emergency Contact Number:                              |  |        |                  |
| Comment:   | <input style="width: 100%;" type="text"/>  |        |                  |
| Corrective Action:                                     | <input style="width: 100%;" type="text"/>  |        | Date: _____      |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                  |
| <b>Spills:</b>   |  |        |                  |
| Type   | Area   | Volume |                  |
| In Containment: No                                     |  |        |                  |
| Comment:   | <input style="width: 100%;" type="text"/>  |        |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                  |
| <b>Fencing/:</b>                                       |  |        |                  |
| Type   | PUMP JACK  |        |                  |
| Comment:   | Metal panels around unit and wellhead  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| <b>Equipment:</b>                                      |  |        |                  |
| Type: Deadman # & Marked                               | # 4  |        | corrective date  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type: Pump Jack  | # 1  |        |                  |
| Comment:   | Sentry unit. Pitman arm removed at time of inspection and horsehead is chained to the wellhead |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type: Prime Mover                                      | # 1  |        |                  |
| Comment:   | Arrow gas engine   |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type: Ancillary equipment                              | # 1  |        |                  |
| Comment:   | Gas scrubber   |        |                  |
| Corrective Action:                                     |  |        | Date:            |

**Tanks and Berms:**

| Contents       | # | Capacity | Type           | Tank ID | SE GPS                |
|----------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER | 1 | OTHER    | PBV FIBERGLASS |         | 39.903210,-102.206410 |

Comment: [Fiberglass water tank 50% buried on north side of unit](#)

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Paint**

|                  |         |
|------------------|---------|
| Condition        |         |
| Other (Content)  |         |
| Other (Capacity) | 210bbbs |
| Other (Type)     |         |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

Comment:

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 273992 Type: WELL API Number: 125-08936 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(Herbert 14-9, Shay 41-8, 43-8\) 3300' S @ 39.89347/-102.20355](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Inspector could not adequately assess location and access conditions. However, there were areas of erosion on the access, which consists of a trail through farm ground, CRP and pasture. Access will need maintenance when the conditions allow it

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                                   | URL   |
|--------------|---|---|
| 715203532    | location photo                                | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355901">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355901</a> |
| 715203533    | erosion on access near location               | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355902">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355902</a> |
| 715203534    | erosion and deep tracks on access to location | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355904">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355904</a> |