

Inspection Photos

Location: Slip Rock 11-13 and Slip Rock 11-13 TR

Location ID: 334186

API # 05-071-06807 and 05-071-09199



Photo 1 – Well Placard

Photo 2 – TR wellhead

Inspection Photos

Location: Slip Rock 11-13 and Slip Rock 11-13 TR

Location ID: 334186

API # 05-071-06807 and 05-071-09199



Photo 3 – KV wellhead and equipment

Photo 4 – Stained soils at base of wellhead

Inspection Photos

Location: Slip Rock 11-13 and Slip Rock 11-13 TR

Location ID: 334186

API # 05-071-06807 and 05-071-09199



Photo 5 – Stained soils at base of skid.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources