

Final Reclamation Inspection

August 20th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 317894

Inspection Document #: 714002799

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 1. NAIP aerial imagery (2009) illustrating the well location (red circle), associated tank battery location (blue polygon), and well access roads (black lines).



Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 2. Orthomosaic (drone) imagery taken 8/20/2025 and NAIP aerial imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon). Note: Historical imagery shows a new tank battery facility was built over the old tank battery disturbance.



Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well, well access roads, and presumed flowline).



Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well, well access roads, and presumed flowline).



Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well, well access roads, and presumed flowline).



Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well, well access roads, and presumed flowline).






Photo 7. Close-up orthomosaic (drone) imagery taken 8/20/2025 illustrating the well location (red circle), well access roads, presumed flowline, and a portion of the associated tank battery (blue polygon).

Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 8. Drone aerial imagery taken south of the tank battery location, facing north (displaying the TB). Sunted crop to the west of the well pad disturbance is not related to oil and gas operations.



Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 9. Drone aerial imagery taken west of the tank battery location, facing east (displaying TB).



Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 10. Drone aerial imagery taken north of the tank battery location, facing south (displaying the TB).



Inspection Photos

Location Name: Lucas Wilson Unit 1

Location ID: 317894



Photo 11. Drone aerial imagery taken east of the tank battery location, facing west (displaying the TB). No evidence of previous tank battery disturbance observed at newly built tank battery facility.

