

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2025

Submitted Date:

12/02/2025

Document Number:

710500641

**FIELD INSPECTION FORM**

Loc ID: 334186 Inspector Name: Sanchez, Chris On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89227	WELL	PR	01/01/2019	CBM	071-06807	SLIPROCK 11-13	EI
289372	WELL	SI	03/01/2025	CBM	071-09199	SLIPROCK 11-13 TR	EI

**General Comment:**

This is an Environmental Inspection for the Slip Rock 11-13 and Slip Rock 11-13 TR well location located in Las Animas County, Colorado

Slip Rock 11-13  
API # 05-071-06807  
Slip Rock 11-13 TR  
API # 05-071-09199  
Location ID 334186

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Placard on meter house		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	_____

**Good Housekeeping:**

Type	OTHER		
Comment:	At the time of inspection, impacted soils were observed at the base of the KV wellhead.  Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

				corrective date
Type: Compressor	# 1			
Comment:	At the time of inspection, impacted soils were observed at the base of the Liquid Ring skid pan.  Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			
Corrective Action:		Date:		

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 89227 Type: WELL API Number: 071-06807 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289372 Type: WELL API Number: 071-09199 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Pit Facility ID: 256177 was closed under Remediation Project # 7210</a>	sanchezcc	12/02/2025
<a href="#">Pit Facility ID: 293318 was closed under Remediation Project # 7211</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500642	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7357009">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7357009</a>