

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404457337

Date Received:  
12/02/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Karen Adams	303-916-1170	Adams@kt-res.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 715501351

Inspection Date: 03/03/2025

FIR Submit Date: 03/03/2025

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: KT RESOURCES LLC

Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

**LOCATION - Location ID: 336462**

Location Name: ANT HILL UNIT-62N97W Number: 36NWNW County: \_\_\_\_\_

Qtrqtr: NWN Sec: 36 Twp: 2N Range: 97W Meridian: 6  
W

Latitude: 40.105419 Longitude: -108.231976

**FACILITY - API Number: 05-103- -00 Facility ID: 336462**

Facility Name: ANT HILL UNIT-62N97W Number: 36NWNW

Qtrqtr: NWN Sec: 36 Twp: 2N Range: 97W Meridian: 6  
W

Latitude: 40.105419 Longitude: -108.231976

**CORRECTIVE ACTIONS:**

1 CA# 202952

Corrective Action: All load lines or tank valves that can be used as a load line will be capped or plugged.

Date: 03/12/2024

Response: CA COMPLETED

Date of Completion: 03/14/2025

Operator Comment: Load line plugged

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**2** CA# 202953

Corrective Action: Remove and properly dispose of oily waste and contaminated soil.

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 03/14/2025

Operator Comment:

Treated stains with Gator

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**3** CA# 202954

Corrective Action: Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 03/14/2025

Operator Comment:

Replaced relief vent

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**4** CA# 202955

Corrective Action: Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.

Date: 03/17/2024

Response: CA COMPLETED

Date of Completion: 05/25/2025

Operator Comment:

Meter calibrated

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**5** CA# 202956

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Date: 05/03/2023

Response: CA COMPLETED

Date of Completion: 03/14/2025

Operator Comment:

Bladed location

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karen Adams

Signed: \_\_\_\_\_

Title: Manager

Date: 12/2/2025 10:03:29 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404457337	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files