

## Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/20NESE

Location ID: 323807

Date: 11/25/2025



Location Overview/Lack of Stabilization – Photo #01723


Location – Photo #01726

## Audit Photos


Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/20NESE

Location ID: 323807

Date: 11/25/2025



Nov 25, 2025 at 10:18:29  
+39.517441,-108.570148  
19422-19874 CR-204  
De Beque CO 81630  
United States



Nov 25, 2025 at 10:17:13  
+39.517059,-108.570172  
19422-19874 CR-204  
De Beque CO 81630  
United States

Location – Photo #01728

Location – Photo #01725

## Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/20NESE

Location ID: 323807

Date: 11/25/2025



Lack of Stabilization – Photo #01724



Lack of Stabilization/Insufficient Tracking BMPs – Photo #01729

## Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/20NESE

Location ID: 323807

Date: 11/25/2025



Lack of Stabilization on Lease Road – Photo #01774

Lack of Stabilization on Lease Road – Photo #01775