

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2025

Submitted Date:

12/03/2025

Document Number:

717300628

FIELD INSPECTION FORM

Loc ID 309938 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275035	WELL	SI	05/01/2022	GW	123-25619	COULTER 15-12	PA
309938	LOCATION	AC			-	COULTER-62N66W 12SWSE	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 275035 Type: WELL API Number: 123-25619 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 309938 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Coulter 15-12); ECMC form 42 notice of start of plugging operations doc #404398429 received on 10/21/2025. Wellhead flowline has been AIP (removed); No flowlines/ risers observed at PA area. Remediation work is in progress.	maclarej	12/03/2025
As outlined on ECMC form 19 spill report Doc #404439835 received on 11/20/2025: While conducting flowline removal activities at the Coulter 15-12 wellhead, historically impacted soil was discovered at flowline sample FL-B03. The volume of the release is unknown. The flowline has been permanently removed.	maclarej	12/03/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300632	PA well and signage	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7357859
717300633	PA well; debris, No FL riser	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7357860