

Photo Log: Harper USX EE27-07D Multi Location ID 423538



ECMC
40.5466, -104.64024, 4811.6ft
12/02/2025 14:21:52



ECMC
40.54664, -104.6402, 4817.1ft
12/02/2025 14:22:45

Evidence of overfill at produced water vessel. At least two tears in the liner are observed near the southern and northern most produced water vessels.



Photo Log: Harper USX EE27-07D Multi Location ID 423538



Harper USX EE 27-1D, with TA status



Location of Harper USX EE27-23D, which is plugged and buried; Harper USX EE27-15D is in background

