

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2025

Submitted Date:

12/03/2025

Document Number:

719700317

**FIELD INSPECTION FORM**

Loc ID 427667 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427673	WELL	PR	03/01/2022	OW	123-35071	WALCKER AC17-64HN	PR

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Wellsite(s): Coolant, Motor oil; Placards.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Posted.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Iron pipe.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Active.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Wellsite(s): 1: Motor oil drum w/ drip containment. 1: Coolant drum w/ drip containment.		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack. Surrounded by protective shed. Active.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.573043,-104.470042
Comment:	Centralized Battery serves 1 Location ID (427667). (Well(s): 1: Producing   PR). Centralized Battery serves 1 Tank Battery Facility ID (483176).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 427673 Type: WELL API Number: 123-35071 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/> Date: _____						
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p><b>CECMC Audit Report Synopsis:</b></p> <p>On TUE 12/02/2025 at approximately 15:27 hrs. I, Bret Evins, conducted an onsite audit at:                      Operator Name: NOBLE ENERGY INC                      Location Name: WALCKER/AC17-64HN                      Location ID: 427667                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this report.                      Location County: Weld County, Colorado                      Weather: Mostly Cloudy, dry.</p> <p>While there, I observed:                      Well(s): 1: Producing   PR.                      Battery: Active.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	12/03/2025
<p>This is a WELL audit.                      Well(s): 1: Producing   PR.                      Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (427667).                      (Well(s): 1: Producing   PR).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (483176).</p> <p>Reference (Associated Well(s), Battery / Facility Audits):                      A.) Field Audit Report doc. #719700317 and/or Location ID #427667 for PR Well(s) info.                      B.) Field Audit Report doc. #719700319 and/or Facility ID #483176 for Battery / Facility, Equipment info.</p>	evinsb	12/03/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700318	Audit photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7358788">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7358788</a>