

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2025

Submitted Date:

12/03/2025

Document Number:

713302370

FIELD INSPECTION FORM

Loc ID 332734 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CHEVRON		stephaniebittner@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248743	WELL	SI	12/01/2023	GW	123-16545	KINSMAN 34-18	SI

General Comment:

[well site inspection](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 2		corrective date
Comment:	automation panels		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 248743 Type: WELL API Number: 123-16545 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: WATER H20

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>Audit of scout card and related documents</u> <u>Routine inspection</u>	kesterm	12/03/2025
<u>This inspection does not nullify any orders or NOAV from the ECMC</u>		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302371	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7360108