

Inspection Photos

Loc: 483009

Operator: BNL (ENTERPRISE) INC

Inspection Date: 12/2/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. Vehicles are driving outside of the road causing unnecessary disturbance. The road needs to be repaired and maintained. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025

Inspection Photos



Photo 2. Facing north along the access road. This area has been disturbed with a dozer pushing topsoil up onto the road. The topsoil is loose and not adequate for stabilization of the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025

Inspection Photos



Photo 3. Facing toward the area where topsoil was pushed onto the road. The topsoil is loose and is not an adequate road base material.




Photo 4. The soil is loose which will cause dust and vehicle tracking.



Inspection Photos



Photo 5. Facing north along the access road. Vehicles are driving outside of the road causing unnecessary disturbance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025

Inspection Photos



Photo 6. Facing north along the access road. Vehicles are driving outside of the road causing unnecessary disturbance. Vehicle tracking is occurring along the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025

Inspection Photos



Photo 7. Facing northeast. Topsoil was mixed and pushed up to the road which is not sufficient material to stabilize the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025

Inspection Photos



Photo 8. Drone aerial photo facing north along the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025

Inspection Photos



Photo 9. Drone aerial photo facing southeast toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025

Inspection Photos



Photo 10. Facing south toward the well pad location..



Inspection Photos



Photo 11. Facing southeast corner of the location. This sediment trap has filled in with sediment and needs to be cleaned out and maintained.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025

Inspection Photos



Photo 12. Southwest corner of the location facing north. The topsoil has not been seeded and stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 12/2/2025