

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2025

Submitted Date:

12/05/2025

Document Number:

708907932

FIELD INSPECTION FORM

Loc ID 335566 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	
Katz, Aaron		aaron.katz@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284331	WELL	PR	03/01/2019	GW	045-12149	CHEVRON 1N-4D	PR
284332	WELL	SI	08/01/2025	GW	045-12148	CHEVRON 8I-5D	SI
284333	WELL	PR	03/01/2019	GW	045-12147	CHEVRON 8K-5D	PR
284334	WELL	PR	03/01/2019	GW	045-12146	CHEVRON 8L-5D	PR

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 284331 Type: WELL API Number: 045-12149 Status: PR Insp. Status: PR

Producing Well

Comment: After review of well records and COGIS Online, the "as drilled" coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - coordinates appear to be off by approximately 40 ft

Additionally the "as drilled" coordinates for the CHEVRON 8I-5D, CHEVRON 8K-5D & CHEVRON 8L-5D wells appear to be incorrect/not in compliance with CECMC Rules 216 & 414

Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action: **Comply with CECMC Rules 216 & 414** Date: 01/04/2026

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284332 Type: WELL API Number: 045-12148 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Additionally the CHEVRON 1N-4D & CHEVRON 8K-5D wells also lack wellbore diagrams/not in compliance with CECMC Rule 420

After review of well records and COGIS Online, the "as drilled" coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - coordinates appear to be off by approximately 10-12 ft

Corrective Action: **Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17** Date: 01/04/2026

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284333 Type: WELL API Number: 045-12147 Status: PR Insp. Status: PR

Producing Well

Comment: After review of well records and COGIS Online, the "as drilled" coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - coordinates appear to be off by approximately 12-14 ft

Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284334 Type: WELL API Number: 045-12146 Status: PR Insp. Status: PR

Producing Well

Comment: After review of well records and COGIS Online, the "as drilled" coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - coordinates appear to be off by approximately 29 ft

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 12/05/2025 at approximately 11:52 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW Location # 335566 in Garfield County Colorado. Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 23 yards from Parachute Creek.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - "as drilled" coordinates for the CHEVRON 1N-4D, CHEVRON 8I-5D, CHEVRON 8K-5D & CHEVRON 8L-5D wells appear to be incorrect - Comply with CECMC Rules 216 & 414 with a CA date of 01/04/2026</p> <p>2. Inspected Facilities - CHEVRON 1N-4D, CHEVRON 8I-5D & CHEVRON 8K-5D wells lack wellbore diagrams - Comply with CECMC Rule 420 with a CA date of 01/04/2026</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of desktop inspection/audit report.</p> <p>Split pad/Remote location - Shared facilities with location # 335766</p>	smelserw	12/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708907933	Inspection/Audit 708907932 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7362187