

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2025

Submitted Date:

12/06/2025

Document Number:

719700321

FIELD INSPECTION FORM

Loc ID 427751 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427714	WELL	PR	09/01/2025	OW	123-35093	BASHOR AC 18-62HN	PR

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Wellsite(s): Coolant, Motor oil; Placards.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Iron pipe.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron pipe.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack. Surrounded by protective shed. Active.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Wellsite(s): 1: Motor oil drum w/ drip containment. 1: Coolant drum w/ drip containment.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Active.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.568410,-104.470810
Comment:	Centralized Battery serves 1 Location ID (427751). (Well(s): 1: Producing PR). Centralized Battery serves 1 Tank Battery Facility ID (483175).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 427714 Type: WELL API Number: 123-35093 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/16/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/> Date: _____						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 12/02/2025 at approximately 15:48 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR AC/18-62HN Location ID: 427751 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	12/06/2025
<p>This is a WELL audit. Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (427751). (Well(s): 1: Producing PR).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (483175).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700321 and/or Location ID #427751 for PR Well(s) info. B.) Field Audit Report doc. #719700323 and/or Facility ID #483175 for Battery / Facility, Equipment info.</p>	evinsb	12/06/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700322	Audit photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7363356