

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2025

Submitted Date:

12/06/2025

Document Number:

719700323

FIELD INSPECTION FORM

Loc ID 427751 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483175	TANK BATTERY	AC	11/07/2022		-	Bashor AC 18-62HN	AO

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Battery site: Nitrogen, Propane; Placards.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:			Date:
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:			Date:
Type:	Emission Control Device	# 1	
Comment:	1: Crude oil storage vapor line combustor(s). Controls crude oil storage vapors. Pilots: ON.		
Corrective Action:			Date:
Type:	Bird Protectors	# 2	
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Battery site: 1: Nitrogen tank for instrument air. 1: Propane tank. 1: ECD scrubber(s).		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	1: Gas Sales, Master; (Chevron). Calibration card(s) indicates calibration <= 1 year. Last calibration: 03/27/2025.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 1 Location ID (427751). (Well(s): 1: Producing PR). Centralized Battery serves 1 Tank Battery Facility ID (483175).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Berms shared w/ crude oil tank(s), produced H2O tank(s), vault(s).			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST			
Comment: Partially insulated.						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil tank(s), produced H2O tank(s), vault(s).				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	5	300 BBLs	STEEL AST		40.568410,-104.470810	
Comment: Equalizer line(s) connect 5 of 5 crude oil tank(s).						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil tank(s), produced H2O tank(s), vault(s).				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
123-35093

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 483175 Type: TANK API Number: - Status: AC Insp. Status: AO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Comment: <input style="width: 90%;" type="text"/>						
Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 12/02/2025 at approximately 15:59 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Facility Name: Bashor AC 18-62HN/ Facility ID: 483175 Location Name: BASHOR AC/18-62HN Location ID: 427751 Well Name(s): See photo(s) #6 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #6 attached to this report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	12/06/2025
<p>This is a BATTERY audit. Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (427751). (Well(s): 1: Producing PR).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (483175).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700321 and/or Location ID #427751 for PR Well(s) info. B.) Field Audit Report doc. #719700323 and/or Facility ID #483175 for Battery / Facility, Equipment info.</p>	evinsb	12/06/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700324	Audit photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7363357