

Inspection Photos
Location Name: Shiner 44-22
API Number: 125-11391



1. Lease sign at well location.



2. View of wellhead. Note Bradenhead valve missing plug.

Inspection Photos
Location Name: Shiner 44-22
API Number: 125-11391



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: Shiner 44-22
API Number: 125-11391



5. View of Dehydrator (Drip Bottle) on gas meter run inlet. Note visible moisture on bottle.



6. View of valve on Dehydrator (Drip Bottle). Valve will not full close and plug seat is cross threaded.

Inspection Photos
Location Name: Shiner 44-22
API Number: 125-11391



7. Damage to Meter Shed roof.



8. Gas meter inside meter shed.

Inspection Photos
Location Name: Shiner 44-22
API Number: 125-11391



9. View of open ended stubbed up poly pipe at well location.



10. Gathering location overview.