

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2025

Submitted Date:

12/02/2025

Document Number:

715203502

FIELD INSPECTION FORM

Loc ID 303628 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253398	WELL	PR	01/03/1991	GW	125-07275	ODELL 3-8	PR

General Comment:

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

Location

Lease Road:			
	Type	Access	
	comment:	Dirt road through pasture	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	TANK LABELS/PLACARDS	
	Comment:	Metal sign by water tank	
Corrective Action:			Date:
	Type	WELLHEAD	
	Comment:	Lease sign by unit	
Corrective Action:			Date:

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type	PUMP JACK	
	Comment:	Metal panels around unit and wellhead	
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:		Kohler gas engine	
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:		Gas scrubber	
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:		Churchill unit	
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.900660,-102.209670
Comment: Fiberglass water tank 50% buried					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 253398 Type: WELL API Number: 125-07275 Status: PR Insp. Status: PR

Producing Well

Comment: Producing. Casing production. Central meter run for (Odell 3-8, 34-8, Shay 33-8, Bruder 1-8) 2500' S @ Shay 33-8

Corrective Action: Audible gas leak was detected at wellhead. The tubing packing is leaking around the tubing and the flange needs tightened

Date: 12/03/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404456025	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355446
715203516	pumping unit and water tank	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355440
715203517	access erosion	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7355441