

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC D.F. ROOTH #5 & D.F. ROOTH #6 PAD

Location ID: 336541

Date: 11/20/2025



Photo # 4430 Entrance to location



Photo # 4431 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC D.F. ROOTH #5 & D.F. ROOTH #6 PAD

Location ID: 336541

Date: 11/20/2025



Photo # 4432 Location



Photo # 4435 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC D.F. ROOTH #5 & D.F. ROOTH #6 PAD

Location ID: 336541

Date: 11/20/2025



Photo # 4438 Location



Photo # 4444 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC D.F. ROOTH #5 & D.F. ROOTH #6 PAD

Location ID: 336541

Date: 11/20/2025



Photo # 4441 Tunnel erosion near D.F. ROOTH #5 wellhead/needs maintenance.



Photo # 4443 Tunnel erosion near D.F. ROOTH #5 wellhead/needs maintenance.