

## Inspection Photos

Location Name: Kinder Morgan McElmo Dome Unit 35-38-19 HE-2

API # 05-083-06387



**1. Entrance to well pad.**



**2. Well head and meter. Down fence is on left.**



**3. Close up showing down fence in vegetation on left.**

**4. Interim reclamation vegetation in fence off area outside of oval looks healthy, undesirable vegetation not an issue. Note presence of rig tie down marked by orange plastic tubing.**



**5. Photo of well head and meter.**