

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2025

Submitted Date:

12/08/2025

Document Number:

721100013

FIELD INSPECTION FORM

Loc ID 313538 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LLC
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224391	WELL	PR	09/01/2025	CO2	083-06456	MCELMO DOME 15-37-18 YD-3	PR

General Comment:

On November 25, 2025, I, James Blair performed an inspection on this well at ~12:15 PM. The weather was clear and approximately 60F. It had rained the last couple days and the roads were wet but not muddy. This is a routine surface inspection and audit of the electronic well file.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Location sign on lease road about 200 ft from well head. See Photo 1.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	24 Hour Contact = 970-882-5522. Emergency services = 911. See photo 1.	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

				corrective date
Type: Bradenhead	# 1			
Comment:				
Corrective Action:		Date:		
Type: Gas Meter Run	# 1			
Comment:	Meter is disconnected. Bare wires exposed. See photos 5 and 6.			
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	Well Head Assembly.			
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	Expanded metal grating over cellar at well head to protect wildlife.			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224391 Type: WELL API Number: 083-06456 Status: PR Insp. Status: PR

Producing Well

Comment: Production appears to be intermittent.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [Adequate. See photos 1 and 2.](#)

Corrective Action:

Date: 11/26/2025

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100023	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7366396