

Inspection Photos

API: 009-06014

Operator: JONES ENERGY LTD

Inspection Date: 12/8/2025

County: BACA



Inspection Photos



Photo 1. Drone aerial photo facing southwest toward the access road. The dark vegetation in this area is undesirable weeds (Kochia).



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06014 | Date: 12/8/2025

Inspection Photos



Photo 2. Drone aerial photo facing southwest along the former access road. This portion of the road has re-established desirable perennial vegetation. The lighter colored vegetation is Sand dropseed and Blue grama.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06014 | Date: 12/8/2025

Inspection Photos



Photo 3. Drone aerial photo facing southwest at the former wellsite. The area is bare of vegetation and appears to be impacted from a historical spill from wellsite operations.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06014 | Date: 12/8/2025

Inspection Photos



Photo 4. Drone aerial photo facing northeast at the former wellsite. The area is bare of vegetation and appears to be impacted from a historical spill from wellsite operations.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06014 | Date: 12/8/2025

Inspection Photos




Photo 5. Facing north toward the surrounding native pasture which has a uniform vegetation cover.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources