

Looking along Flowline Facility ID 476033 trench towards the former STATE #3 well. The flowline appears to have been removed. A rope with orange ribbons has been installed on the east side of the trench. Stockpiled soil is visible along the west side of the trench and east of the former well.



 **Frederick, CO, United States**
Lat 40.093578, Long -104.954725
12/02/2025 15:04 GMT-07:00
ECMC : Environmental Inspection

 46°F

 48° NE

 3.0 mph  5033.37 ft  5.31 m

Looking at the former State #3 well. An open excavation is visible. Gray staining is visible in the excavation. Gray staining is visible in the stockpiled soil to the west. A petroleum hydrocarbon odor was observed. The pumping unit has been removed. Multiple residences, a walking path, and a pedestrian are visible in the background.



Frederick, CO, United States

Lat 40.093283, Long -104.954649
12/02/2025 15:04 GMT-07:00
ECMC : Environmental Inspection



46°F

112° SE

3.0 mph

5035.2 ft

4.87 m

Gray staining is visible in the excavation. Gray staining is visible in the stockpiled soil to the west. A petroleum hydrocarbon odor was observed.



Frederick, CO, United States
Lat 40.093215, Long -104.954616
12/02/2025 15:05 GMT-07:00
ECMC : Environmental Inspection


 

 46°F

 188° S

 3.0 mph  5029.89 ft  6.07 m

Looking at the former State #3 well and excavation. Orange construction fencing partially surrounds the excavation at the former well. The pumping unit has been removed. Stockpiles associated with Spill ID 490840 are visible in the background and will be addressed in a separate Field Inspection Report.



Frederick, CO, United States

Lat 40.093114, Long -104.954648

12/02/2025 15:05 GMT-07:00

ECMC : Environmental Inspection



46°F

260° W

3.0 mph

5028.84 ft

6.27 m

Looking at the soil stockpile adjacent to the State #3 well excavation. Gray staining is visible; a petroleum hydrocarbon odor was observed. No liner is visible. Stormwater BMPs are inadequate.



Frederick, CO, United States

Lat 40.093221, Long -104.954529

12/02/2025 15:06 GMT-07:00

ECMC: Environmental Inspection



46°F

237° SW

3.0 mph

5036.91 ft

6.44 m

Looking at the soil stockpile adjacent to the State #3 well excavation. Gray staining is visible; a petroleum hydrocarbon odor was observed. No liner is visible. Stormwater BMPs are inadequate.



 **Frederick, CO, United States**
Lat 40.093266, Long -104.954503
12/02/2025 15:06 GMT-07:00
ECMC : Environmental Inspection

 46°F
 170° S

 3.0 mph  5031.27 ft  6.27 m