

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2025

Submitted Date:

12/10/2025

Document Number:

717300643

FIELD INSPECTION FORM

Loc ID 320391 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203629	WELL	SI	08/01/2018	GW	001-09189	HSR LAWSON 8-3	PA
320391	LOCATION	AC			-	HSR LAWSON-62S66W 3SENE	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 203629 Type: WELL API Number: 001-09189 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 320391 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (HSR Lawson 8-3); ECMC form 42 notice of start of plugging operations doc #404403374 received 10/24/2025. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline pre-abandonment doc #404385260 received 10/14/2025 (OL facility FL's have been removed). No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	12/10/2025
As outlined on ECMC form 19 spill report Doc #404462773 received on 12/07/2025: While conducting facility decommissioning activities at Crestone Peak's Brown 5-3, 31-5, historical impacts were discovered. Lease operators are coached to do routine AVO inspections at all oil and gas facilities.	maclarej	12/10/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300648	Location; View South	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7369394
717300649	Location; View North (OOS 300 bbl AST)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7369395