

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2025

Submitted Date:

12/04/2025

Document Number:

719500702

**FIELD INSPECTION FORM**

Loc ID 334468 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10844

Name of Operator: QB ENERGY OPERATING LLC

Address: 1001 17TH STREET SUITE 1600

City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297471	WELL	PR	11/05/2012	GW	045-16849	FEDERAL 1-14 (ON-1)	PR
297472	WELL	PR	11/28/2012	GW	045-16850	FEDERAL 1-13(ON-1)	PR
297473	WELL	PR	11/28/2012	GW	045-16851	FEDERAL 1-11(ON1)	PR
297474	WELL	PR	02/20/2013	GW	045-16852	FEDERAL 1-15(ON1)	PR
423709	WELL	PR	11/03/2011	GW	045-20792	FEDERAL 36-1H (ON1)	PR

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 12/1/2025 at approximately 15:00, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, Federal/35-16H (ON1) at Location ID #334468 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels missing required information.		
Corrective Action:	Comply with CECMC Signs and Markers Rules.	Date:	01/05/2026

**Emergency Contact Number:**

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash/debris near tank battery.		
Corrective Action:	Remove trash/debris from location.	Date:	12/12/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	<a href="#">Concrete barriers</a>		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	<a href="#">Concrete barriers</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	<a href="#">Summit Midstream</a>		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	<a href="#">Form 4 Sundry (Doc #404376750) submitted by Operator for updated equipment inventory/facility layout.</a>		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Chemical tank</a>		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Catalytic heater in Summit Midstream meter house.</a>		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS

CONDENSATE	3	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 297471 Type: WELL API Number: 045-16849 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297472 Type: WELL API Number: 045-16850 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297473 Type: WELL API Number: 045-16851 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297474 Type: WELL API Number: 045-16852 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 423709 Type: WELL API Number: 045-20792 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
		Gravel				
Compaction						
		Ditches				
Berms						
		Culverts				
Gravel						
		Compaction				
				Material Handling And Spill Prevention		

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) Tank labels missing required information 2) Trash/debris on location</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrism	12/04/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404461209	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7361084">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7361084</a>
719500703	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7361081">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7361081</a>