

Inspection Photos  
Location Name: C. Korf 2-19  
API Number: 125-06977



1. Lease sign at well location.



2. View of wellhead. Note open-ended line on tubing water leg.

**Inspection Photos**  
**Location Name: C. Korf 2-19**  
**API Number: 125-06977**



**3. Bridle disconnected from Horsehead.**



**4. Well location overview.**

Inspection Photos  
Location Name: C. Korf 2-19  
API Number: 125-06977



5. Lease sign at gathering location.



6. Gas meter inside meter shed.

**Inspection Photos**  
**Location Name: C. Korf 2-19**  
**API Number: 125-06977**



**7. Flowline riser at gathering location with bolted cap.**



**8. Gathering location overview.**