

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2025

Submitted Date:

12/05/2025

Document Number:

715801692

FIELD INSPECTION FORM

Loc ID 328403 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------------|-------|----------------------------------|---------------------------------|
| Santistevan, Brittani | | brittani.santistevan@state.co.us | |
| | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 248150 | WELL | PR | 02/01/2024 | OW | 123-15948 | NUCON 21-12 | PR |

General Comment:

[This is a follow up field audit of the scout card, related documents and the location.](#)

| Location | | | |
|--|--|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Location is in a concrete precast facility. | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Operator information is faded and needs to be updated. | | |
| Corrective Action: | Install sign to comply with Rule 605.g. | | Date: 09/14/2025 |
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: _____ |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | tall vegetation throughout location & around th equipment. | | |
| Corrective Action: | Comply with Rule 606 | | Date: 08/21/2025 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | <input type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Fabricated square tubing. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | electric panel | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | electric motor | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 248150 Type: WELL API Number: 123-15948 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Scout card shows the well as PR most recent PR records show 9-1-25, at the time of this inspection the electric panel is off & valves closed.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/30/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____ Date: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>ECMC Inspection Report Summary. On Friday 12-5-2025 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 328403 API #05-123-15948 Well name: Nucon 21-25 County: Weld Weather: Cloudy & cold Temp: 28* Location: Snow covered While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues from FIR Doc # 715801353 have not been addressed: 606 housekeeping: vegetation CA date 8-21-2025. 605.g signs: operator information CA date 9-14-2025 See attached photos. Due to Non-Compliance with ECMC rules, this audit/inspection will be referred to ECMC Enforcement.</p> | revasr | 12/05/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404462531 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7362664 |
| 715801693 | Location photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7362653 |