

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2025

Submitted Date:

12/12/2025

Document Number:

713302393

FIELD INSPECTION FORM

Loc ID 326865 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		ports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245994	WELL	TA	04/01/2020	GW	123-13790	OCOMA C17-13	TA

General Comment:

well site inspection

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	missing		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 01/12/2026

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	metal panels, heavy conrer post, one panel piled on well head		
Corrective Action:			Date:

Equipment:				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	automation panels			
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	piped to surface			
Corrective Action:			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 245994 Type: WELL API Number: 123-13790 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Form 6 on file doc 4033118488, 8-17-2025 well head disconnected with fittings plugged

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents conducted on-site inspection, Location: Ocoma C17-13 Operator: Noble API#: 123-13790 County: Weld While there, I observed well site with Form 6 on file doc 4033118488, 8-17-2025 well head disconnected with fittings plugged During this inspection the following possible compliance issues were observed:</p> <p>Sign, Rule 605g, corrective action date 1-12-2026</p> <p>Weather conditions: sunny and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	12/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302394	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7372871