

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2025

Submitted Date:

12/12/2025

Document Number:

713302387

**FIELD INSPECTION FORM**

Loc ID 327946 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
|              |       | ports@chevron.onmicrosoft.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 247553      | WELL | TA     | 01/01/2025  | GW         | 123-15350 | ARENS 23-2G   | TA          |

**General Comment:**

well site inspection

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | good     |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |                                          |       |                                          |
|--------------------|------------------------------------------|-------|------------------------------------------|
| Comment:           | <input style="width: 95%;" type="text"/> |       |                                          |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 80%;" type="text"/> |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                                     |       |  |
|--------------------|-------------------------------------|-------|--|
| Type               | WELLHEAD                            |       |  |
| Comment:           | metal panels with heavy corner post |       |  |
| Corrective Action: |                                     | Date: |  |

**Equipment:**

|                    |                  |       |                 |
|--------------------|------------------|-------|-----------------|
|                    |                  |       | corrective date |
| Type: Plunger Lift | # 1              |       |                 |
| Comment:           |                  |       |                 |
| Corrective Action: |                  | Date: |                 |
| Type: Bradenhead   | # 1              |       |                 |
| Comment:           | piped to surface |       |                 |
| Corrective Action: |                  | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 247553 Type: WELL API Number: 123-15350 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: FLOWLINE AVAILABLE

Comment: Form 6A on file doc 403815939, 6-6-2024 well head disconnected with fittings plugged

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 02/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment                                                                                                                                                                              | User    | Date       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|------------|
| <a href="#">Audit of scout card and related documents</a><br><a href="#">Form 6A on file doc 403815939, 6-6-2024</a><br><a href="#">well head disconnected with fittings plugged</a> | kesterm | 12/12/2025 |
| <a href="#">Routine inspection</a>                                                                                                                                                   |         |            |
| <a href="#">This inspection does not nullify any orders or NOAV from the ECMC</a>                                                                                                    |         |            |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL                                                                                                                                                                 |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 713302388    | site pic    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7372868">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7372868</a> |