

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2025

Submitted Date:

12/12/2025

Document Number:

708908007

**FIELD INSPECTION FORM**

Loc ID 311567 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	
Ramsey, Scott		scott.ramsey@state.co.us	
Koch, Benjamin		bzkoch@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210900	WELL	PR	12/01/1990	GW	045-06658	DOE 1-W-19	PR

**General Comment:**

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

**Inspected Facilities**

Facility ID: 210900 Type: WELL API Number: 045-06658 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection/Audit Report Summary</b>                      On 12/12/2025 at approximately 17:45 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop follow up inspection/audit of TEP ROCKY MOUNTAIN LLC DOE 1-W-19                      Location # 311567 in Garfield County Colorado.                      Please refer to desktop inspection/audit 708907862 conducted on 11/10/2025, previous corrective action has been completed.                      Wellbore diagram submitted by operator on 11/19/2025                      Location is within High Priority/Density Habitat areas.                      Location is approximately 140 yards from a creek/drainage that contributes to the Colorado River.</p> <p>This is a summary of desktop follow up inspection/audit report.</p> <p>Dual lease, shared location with the DOE 1-M-19, location # 311545</p>	<p>smelserw</p>	<p>12/12/2025</p>