

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/08/2025

Submitted Date:

12/08/2025

Document Number:

716301790

**FIELD INSPECTION FORM**

Loc ID 308576 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**Findings:**

- 11 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone        | Email             | Comment                         |
|---------------|--------------|-------------------|---------------------------------|
| BACA, DAVE    | 719-859-4066 | dbaca@ogrisop.com | <a href="#">All Inspections</a> |
| B WARD, GIENA |              | gward@ogrisop.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 274793      | WELL | PR     | 04/25/2005  | GW         | 071-08253 | HILL RANCH 36-13 | PR          |

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | PHOTO 4 & 5 : IMPACTED OIL NEAR PRIME MOVER SKID.   |       |            |
| Corrective Action: | Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D.   | Date: | 12/15/2025 |
| Type               | OTHER   |       |            |
| Comment:           | PHOTO 6: PACKING IS LEAKING ON TBG.<br>PHOTO 7: PRIME MOVER IS BLOWING OIL OUT OF EXHAUST PIPES.  |       |            |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Engineer, operate, and maintain equipment within the manufacturer's recommended specifications per Rule 608.e. CA DATE 12-9-2025. | Date: | 12/09/2025 |

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |
|                |      |        |  |

In Containment: No

Comment:

Multiple Spills and Releases?

| <b>Equipment:</b>         |               |       | corrective date |
|---------------------------|---------------|-------|-----------------|
| Type: Deadman # & Marked  | # 4           |       |                 |
| Comment:                  |               |       |                 |
| Corrective Action:        |               | Date: |                 |
| Type: Vertical Separator  | # 1           |       |                 |
| Comment:                  |               |       |                 |
| Corrective Action:        |               | Date: |                 |
| Type: Prime Mover         | # 1           |       |                 |
| Comment:                  |               |       |                 |
| Corrective Action:        |               | Date: |                 |
| Type: Bradenhead          | # 1           |       |                 |
| Comment:                  | IS ACCESSABLE |       |                 |
| Corrective Action:        |               | Date: |                 |
| Type: Ancillary equipment | # 1           |       |                 |
| Comment:                  |               |       |                 |
| Corrective Action:        |               | Date: |                 |
| Type: Progressive Cavity  | # 1           |       |                 |
| Comment:                  |               |       |                 |

|                     |   |       |            |
|---------------------|---|-------|------------|
| Corrective Action:  |   | Date: |            |
| Type: Gas Meter Run | # 1   |       |            |
| Comment:            | CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. |       |            |
| Corrective Action:  |   | Date: |            |
| Type: Compressor    | # 1   |       |            |
| Comment:            | Vacuum pump observed on well without ECMC approval.                       |       |            |
| Corrective Action:  | Provide ECMC with documentation showing approval of use of vacuum pump.   | Date: | 12/22/2025 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 274793 Type: WELL API Number: 071-08253 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/12/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Gravel           | Pass            | Culverts                | Pass                  |               |                          |         |

Comment: PHOTO 8: OILY WASTE IS PRIME MOVER SKID.

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 12/09/2025

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 292648      Lat: 37.035020      Long: -104.953800

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

Lining:

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

Fencing:

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

Netting:

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

**ECMC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p>ECMC Inspection Report Summary<br/>                     On Tuesday 12-8-2025 at approximately 12:58, I Tom Beardslee<br/>                     Conducted an on-site inspection an Evergreen Natural Resources location HILL RANCH 36<br/>                     -13<br/>                     API# 05-071-08253 in Las Animas County Colorado.<br/>                     While there, I observed production operation.<br/>                     During this inspection the following possible compliance issues were observed:<br/>                     IMPACTED SOIL, RULE 1002,,(2).D. CA DATE 12-15-2025. PACKING LEAK &amp; OIL<br/>                     BLOWING OUT OF PRIME MOVER EXHAUST, Rule 608.e. CA DATE 12-9-2025. OILY<br/>                     WASTE IN PRIME MOVER SKID, RULE 1002..(2).D &amp; 1002.f.(2)B, CA DATE 12-9-2025.<br/>                     A follow up on this site inspection needs to be conducted to ensure the<br/>                     Compliance issues have been corrected to comply with ECMC rules.</p> | beardslt | 12/08/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description             | URL   |
|--------------|-------------------------|---|
| 404464483    | INSPECTION<br>SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365423">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365423</a> |
| 716301791    | INSP. PHOTOS            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365418">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365418</a> |