

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/17/2025

Submitted Date:

12/08/2025

Document Number:

717100414

FIELD INSPECTION FORM

Loc ID 319331 Inspector Name: Rollins, Grace On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Graber, Nikki		nikki.graber@state.co.us	
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer
,		ECMCInspections@Oxy.com	All Inspections
Anderson, Laurel		laurel.anderson@state.co.us	
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
319331	LOCATION	AC			-	MARKHAM-64N68W 15SWNW	EI
486999	SPILL OR RELEASE	CL	05/02/2024		-	Markham 1 SEP Historical Release	EI

General Comment:

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 486999 and Remediation Project # 34346. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Site/Spill Name: MARKHAM-64N68W 15SWNW

Spill ID: 486999

Remediation Project #: 34346

Location ID: 319331

Reported Date of Discovery: 5/2/2024

Date of Inspection: 11/17/2025

Weather: Partly cloudy, 16 mph winds, 59°F

Current site status:

- Crops in the field adjacent to the location have been harvested.
- A shallow excavation/depression is visible at the spill location.
- A combination of orange construction fencing and metal panel fencing surround the spill location.
- Weeds are visible throughout the fenced area.
- Trash (black plastic sheet) is visible within the fenced area.
- Signage with emergency contact number is visible.

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash (black plastic sheet) is visible within the fenced area.		
Corrective Action:	Comply with Rule 606.	Date:	12/15/2025
Type	WEEDS		
Comment:	Weeds are visible throughout the fenced area.		
Corrective Action:	Comply with Rule 606.	Date:	12/15/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 319331 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 486999 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Remediation Project # 34346 was created for decommissioning of the MARKHAM-64N68W 15SWNW facility. Spill ID 486999 was created to address the remediation of impacts identified at the former separator. A shallow excavation/depression is visible at the spill location. Crops in the field adjacent to the location have been harvested.

Quarterly reporting is required under Remediation Project # 34346. The last Form 27 for this project was submitted 11/26/2025 and was denied by ECMC on 12/04/2025 due to the Operator reporting that additional investigation/remediation was pending crop harvest (Document # 404434342); a replacement Form 27 has not been received as of 12/8/2025.

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide a replacement Form 27 for Remediation Project # 34346. Date: 12/04/2025

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404464487	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365425
717100415	ECMC Photo Log - MARKHAM-64N68W 15SWNW - 11.17.2025	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365420