

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2025

Submitted Date:

12/08/2025

Document Number:

717100416

FIELD INSPECTION FORM

Loc ID 330930 Inspector Name: Rollins, Grace On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Anderson, Laurel		laurel.anderson@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
,		ECMCInspections@Oxy.com	All Inspections
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256583	WELL	PA	04/23/2025	GW	123-19891	Herman L 32-13Ji	EI
490147	SPILL OR RELEASE	CL			-	Herman L 32-13 JI Flowline	EI

General Comment:

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 490147 and Remediation Project # 490147. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Site/Spill Name: Herman L 32-13 JI Flowline

Spill ID: 490147

Remediation Project #: 38245

Well API #: 05-123-19891

Reported Date of Discovery: 5/7/2025

Date of Inspection: 12/04/2025

Weather: Foggy, 17°F

Current site status:

Due to access and visibility limitations, the exact spill location and flowline path were not inspected. The field surrounding the flowline was inspected from the southwestern corner; crops have been harvested and the field is covered with snow.

See attached corrective actions.

Inspected Facilities

Facility ID: 256583 Type: WELL API Number: 123-19891 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 490147 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Remediation Project # 38245 was created for decommissioning of the Herman L 32-13 JI well and flowline. Spill ID 490147 was created to address the remediation of impacts identified at the flowline riser at the separator. Due to access and visibility limitations, the exact spill location and flowline path were not inspected. The field surrounding the flowline was inspected from the southwestern corner; crops have been harvested and the field is covered with snow.

Quarterly reporting is required under Remediation Project # 38245. The last Form 27 for this project was submitted 11/10/2025 and was denied by ECMC on 12/04/2025 due to the Operator reporting that additional investigation was pending crop harvest (Document # 404381637); a replacement Form 27 has not been received as of 12/8/2025.

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide a replacement Form 27 for Remediation Project # 38245. Date: 12/04/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404464489	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365426
717100417	ECMC Photo Log - Herman L 32-13 JI Flowline - 12.4.2025	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365421