

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2025

Submitted Date:

12/15/2025

Document Number:

708908058

FIELD INSPECTION FORM

Loc ID 323778 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
TEP		ECMCInspectionReports@flywheelenergy.com	
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210784	WELL	PR	09/03/1987	GW	045-06542	MOBIL W-18-27	PR
265373	WELL	PR	04/30/2003	GW	045-08998	PA 314-27	PR

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 210784 Type: WELL API Number: 045-06542 Status: PR Insp. Status: PR

Producing Well

Comment:	Well lacks wellbore diagram/not in compliance with CECMC Rule 420	
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	Date: <u>01/14/2026</u>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 265373 Type: WELL API Number: 045-08998 Status: PR Insp. Status: PR

Producing Well

Comment:	Well lacks wellbore diagram/not in compliance with CECMC Rule 420	
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	Date: <u>01/14/2026</u>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 12/15/2025 at approximately 10:45 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of TEP ROCKY MOUNTAIN LLC MOBIL W-18-27 Location # 323778 in Garfield County Colorado. Location is within High Priority/Density Habitat areas & in close proximity to NSO/Black Bear Habitat areas. Location is within Rule 411a Surface Water Intermediate Buffer.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - MOBIL W-18-27 well lacks wellbore diagram - Comply with Rule 420 with a CA date of 01/14/2026</p> <p>2. Inspected Facilities - PA 314-27 well lacks wellbore diagram - Comply with Rule 420 with a CA date of 01/14/2026</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of desktop inspection/audit report.</p>	smelserw	12/15/2025