

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#		corrective date
Comment: SEE INSP. DOC #716301740 FOR INVENTORY DETAILS			
Corrective Action: <input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Inspected Facilities

Facility ID: 257532 Type: WELL API Number: 071-07018 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
BASED ON DOCUMENTS SUBMITTED BY OPERATOR IN FIRR DOC #404451169 CA'S HAVE BEEN ADDRESSED SEE ATTACHED FORM15'S	beardslt	12/15/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301842	TR FORM 15	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7376839
716301843	ORIG. WELL FORM 15	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7376840