



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:	#		corrective date
Comment: <a href="#">SEE INSP. DOC #716301768 FOR INVENTORY DETAILS</a>			
Corrective Action: <input type="text"/>			Date: <input type="text"/>

**Venting:**

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Flaring:**

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Inspected Facilities**

Facility ID: 271513 Type: WELL API Number: 071-07999 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
BASED ON PHOTOS SUBMITTED IN FIRR DOC #404454900 CA HAS BEEN ADDRESSED. SEE ATTACHED OPERATOR PHOTOS.	beardslt	12/15/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301846	OPERATOR PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7376841">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7376841</a>