

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2025

Submitted Date:

12/09/2025

Document Number:

701104371

FIELD INSPECTION FORM

Loc ID 424971 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424993	WELL	PR	10/12/2012	GW	045-21001	Patterson SG 414-27	EG
424994	WELL	PR	10/12/2012	GW	045-21002	Patterson SG 514-27	EG
424995	WELL	PR	06/30/2012	GW	045-21003	Patterson SG 313-27	EG
424997	WELL	PR	06/30/2012	GW	045-21005	Patterson SG 323-27	EG
424999	WELL	PR	06/30/2012	GW	045-21007	Patterson SG 13-27	EG
425000	WELL	PR	09/13/2012	GW	045-21008	Patterson SG 314-27	EG
425005	WELL	PR	06/30/2012	GW	045-21013	Patterson SG 423-27	EG
425009	WELL	PR	06/30/2012	GW	045-21017	Patterson SG 23-27	EG
425010	WELL	PR	06/30/2012	GW	045-21018	Patterson SG 533-27	EG
425016	WELL	PR	06/30/2012	GW	045-21020	Patterson SG 433-27	EG
425017	WELL	PR	10/12/2012	GW	045-21021	Patterson SG 434-27	EG
425018	WELL	PR	09/13/2012	GW	045-21022	Patterson SG 14-27	EG
425023	WELL	PR	09/13/2012	GW	045-21024	Patterson SG 413-27	EG
425024	WELL	PR	10/12/2012	GW	045-21025	Patterson SG 534-27	EG
425025	WELL	PR	09/13/2012	GW	045-21026	Patterson SG 34-27	EG
425029	WELL	PR	09/13/2012	GW	045-21029	Patterson SG 334-27	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
2-2" dumplines running from separators to production tank is above surface. There is no marker or barricade to prevent damage of dumpline.
Provide protection of exposed flowline. CA Date 12/24/2025

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Flow Line	# 2		corrective date
Comment:	2-2" dumplines running from separators to production tank is above surface. There is no marker or barricade to prevent damage of dumpline.		
Corrective Action:	Provide protection of exposed flowline.		Date: 12/24/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	424993	Type:	WELL	API Number:	045-21001	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	424994	Type:	WELL	API Number:	045-21002	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	424995	Type:	WELL	API Number:	045-21003	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	424997	Type:	WELL	API Number:	045-21005	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	424999	Type:	WELL	API Number:	045-21007	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425000	Type:	WELL	API Number:	045-21008	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425005	Type:	WELL	API Number:	045-21013	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425009	Type:	WELL	API Number:	045-21017	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425010	Type:	WELL	API Number:	045-21018	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425016	Type:	WELL	API Number:	045-21020	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425017	Type:	WELL	API Number:	045-21021	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425018	Type:	WELL	API Number:	045-21022	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425023	Type:	WELL	API Number:	045-21024	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425024	Type:	WELL	API Number:	045-21025	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425025	Type:	WELL	API Number:	045-21026	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	425029	Type:	WELL	API Number:	045-21029	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404465481	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7366480
701104372	Flowline integrity inspection 701104371 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7366478