

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#		corrective date
Comment: see insp. doc #716301633 for detailed inventory			
Corrective Action:			Date: _____

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: _____

Flaring:

Type			
Comment:			
Corrective Action:			Date: _____

Inspected Facilities

Facility ID: 278293 Type: WELL API Number: 071-08423 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 280935 Type: WELL API Number: 071-08608 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
based on photos and documents submitted by operator in firr doc #404474387 ca's have been addressed.	beardslt	12/16/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301853	form 4 vacuum	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7377139
716301854	operator photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7377140