

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404475940

Date Received:  
12/16/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10536

Name of Operator: SMITH ENERGY LLC

Address: 1540 MAIN ST SUITE 218 #334

City: WINDSOR State: CO Zip: 80550

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Chris Smith		smithenergy@live.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718800716

Inspection Date: 08/18/2025

FIR Submit Date: 08/20/2025

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SMITH ENERGY LLC

Company Number: 10536

Address: 1540 MAIN ST SUITE 218 #334

City: WINDSOR State: CO Zip: 80550

LOCATION - Location ID: 474257

Location Name: SALLY CLARKE-64N46W Number: 3NENW County: \_\_\_\_\_

Qtrqtr: NENE Sec: 3 Twp: 4N Range: 46W Meridian: 6

Latitude: 40.349198 Longitude: -102.490100

FACILITY - API Number: 05-125-00 Facility ID: 474257

Facility Name: SALLY CLARKE-64N46W Number: 3NENW

Qtrqtr: NENE Sec: 3 Twp: 4N Range: 46W Meridian: 6

Latitude: 40.349198 Longitude: -102.490100

CORRECTIVE ACTIONS:

1 CA# 207346

Corrective Action: Report spill or release of E&P waste or produced fluids by submitting a Form 19-Initial within 72 hours of spill discovery. Remove free fluids, contact ECMC EPS staff, and control and contain spills/releases and clean up per Rules 912.a. and 912.b. Contact NE EPS Krystal Heibel with any questions (krystal.heibel@state.co.us)

Date: 08/23/2025

Response: CA COMPLETED

Date of Completion: 08/23/2025

Operator Comment: I emailed Katelyn and told her the water on location is not production water, it is 100% rain water. I understand why she thought it may of been production water but the well has been produced for 20 years now and never produced a drop of water. It only flows a little bit of dry natural gas. Hence the reason the tank floated up from the rain water as it was empty and has never had any fluid in the tank since the well was drilled. Tank is not needed and has been removed from location as the picture attached shows.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Smith

Signed: \_\_\_\_\_

Title: Manager

Date: 12/16/2025 4:07:31 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
404475940	FIR RESOLUTION SUBMITTED
404476017	Picture showing tank removed

Total Attach: 2 Files