

WELL NAME: WILLYS 32-8 TR, API #: 071-08688, INSP. # 716301887




PHOTO 1: WELL SIGN



Network: Dec 17, 2025 at 1:32:58 PM MST
Local: Dec 17, 2025 at 1:32:58 PM MST
+37.275056, -104.803897
Los Animas County

PHOTO 2: LOCATION.



Network: Dec 17, 2025 at 1:34:32 PM MST
Local: Dec 17, 2025 at 1:34:32 PM MST
+37.274926, -104.803451
Los Animas County

PHOTO 3: WELLHEAD AND EQUIPMENT.



PHOTO 4: AREA OF IMPACTED SOIL UNDER A LEAK ON DRIVEHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. 1-1-2026. CA DATE 1-1-2026.

Calibration Report

Report Date **12/19/24 2:13 PM**

Collection Time **12/19/24 2:14 PM**

Section 1 - Meter

Device ID **102108688**

System **Contact # 719-846-**

Location **Willys 32-8 Tr**

Field **Raton Basin**

State **Colorado**

Producer **Evergreen Natural**

Purchaser **Colorado Interstate**

Section 2 - Setup

Current Plate Size **0.625**

Pipe Size **2.07**

Atmos. Pressure **11.25**

Pressure Base **14.73**

Tap Type **Flange**

SP Tap Location **Up Stream**

Temperature

Temperature

Specific Gravity

Network: Dec 17, 2025 at 1:37:57 PM MST

Local: Dec 17, 2025 at 1:37:57 PM MST

+37.274919, -104.803442

Los Animas County

PHOTO 5: ANNUAL GAS METER CALIBRATION NEEDS TO BE PERFORMED WITHIN THE NEXT 2 DAY 12/19/2025..



PHOTO 6: DRIVEHEAD IS LEAKING HYDRAULIC FLUID. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Engineer, operate, and maintain equipment within the manufacturer's recommended specifications per Rule 608.e. CA DATE 1/1/2026.