

Inspected FacilitiesFacility ID: 286986 Type: WELL API Number: 071-09003 Status: PR Insp. Status: PR**Producing Well**Comment: pr

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
BASED ON PHOTOS AND DOCUMENTS SUBMITTED IN FIRR DOC #404476443, CA'S HAVE BEEN ADDRESSED. SEE ATTACHED PHOTOS.	beardslt	12/17/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301873	OPERATOR PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380446
716301874	OPERATOR PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380447
716301875	OPERATOR PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380448
716301876	CALIBRATION REPORT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380449