

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/08/2025

Submitted Date:

12/16/2025

Document Number:

721100027

**FIELD INSPECTION FORM**

Loc ID 325694 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215244	WELL	PR	10/15/2021	CBM	067-06849	ARTHUR MASON A 1	PR

**General Comment:**

On Monday, December 08, 2025, James Blair the Simcoe Arthur Mason A1 well, API# 05--067-06849 at 3:30 PM. The weather was clear, and approximately 50°F. It had snowed earlier in the week and the ground was soft.  
Well Location from ECMC GIS: 37.172021°N -107.855152°N.

Location			
<b>Lease Road:</b>			
Type			
comment:	It had snowed recently and the access road was soft, but still drivable without causing deep ruts. See photos 2 and 3.		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign is located near beginning of access road on east side. Still says "BP America" and not Simcoe. See photo 1.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	There are two hazcom placards on the 95bbl Produced Water tank. One indicates a fire hazard of 0 (non-flammable) and the other indicates a hazard level of 4 (highly flammable). Only one of these can be true. One of the placards should be removed and the one that accurately characterizes the produced water should be left. See photos 11 and 12.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 Hour Contact = 970-247-6916. Emergency Contact = 911. See Photo 1.		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Separatore and combustor inside of panel fence.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Panel fence.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 2		corrective date
Comment:	Telemetry, electric panel.		
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:	3" line from wellhead to separator, 2" line from separator to produced water, 2" line from gas meter run to off location.		
Corrective Action:			Date:
Type: Bradenhead	# 1		

Comment: Bird protector = photo 7. Compressor = photo 6. Deadmen no photo. ECD, separator = photo 7. Well head, bradenhead = photo 8.		Date:
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Compressor	# 1	
Comment: Skid mounted compressor operating on wellhead gas. Photo 6.		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment: See photo 13.		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		
Comment: Double-walled, 95 bbl. Note that there are two HazCom labels on the tank, both indicating produced water. one indicating high flamability (4) the other low flamability (0). See photos 11, 23 & 13.					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate			
Comment: Double-walled tank in lieu of berm.				
Corrective Action:				
		Date:		

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 215244 Type: WELL API Number: 067-06849 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Well site and road were driveable, but there were muddy spots because of recent moisture. See photos 2, 3, and 4.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100030	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380997">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380997</a>