

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2025

Submitted Date:

12/10/2025

Document Number:

699507698

FIELD INSPECTION FORM

Loc ID 440017 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10373
Name of Operator: NGL WATER SOLUTIONS DJ LLC
Address: 865 NORTH ALBION ST., STE 400
City: DENVER State: CO Zip: 80220

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Garcia, Dan		dan.garcia@nglep.com	Field Supervisor
Beasley, Nolan		nolan.beasley@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159959	UIC Disposal	AC	05/20/2015		-	NGL C5	AC
440025	WELL	TA	08/11/2021	DSPW	123-40645	NGL C5	TA

General Comment:

UIC Annual audit

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: Weeds unmanaged around wellhead shed, and lease road.

Corrective Action: Comply with rule 606

Date: 01/10/2026

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Metal shed

Corrective Action:

Date:

Equipment:

Type: Bradenhead

1

corrective date

Comment: Plumbed to surface

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 159959 Type: UIC Disposal API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 440025 Type: WELL API Number: 123-40645 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: 489

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DJINJ
 TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 06/28/2021
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: At time of audit no gauges were on wellhead to determine well pressures. MIT due next year.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary On 12/10/25 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- NGL C 5 Company Name- NGL API- 05-123-40645 In Weld County Colorado. While there, I observed TA UIC well During this inspection the following possible compliance issues were observed: Weeds. Rule 606. 1/10/26 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	12/10/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404470563	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7371829
699507699	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7371819