

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2025

Submitted Date:

12/11/2025

Document Number:

720900431

FIELD INSPECTION FORM

Loc ID 336717 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 20 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278475	WELL	PR	06/23/2005	GW	125-09327	LUEKING 11-19 5N46W	PR

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign posted at remote Gas Meter Run.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign at wellhead location.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information posted on Lease sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Production related debris inside wellhead fencing.		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Dried weed and vegetation debris inside well fencing.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:			Date:
Equipment:			
Type: Other	#		corrective date
Comment:	Black poly line stubbed up at gathering location.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Pump Jack welded steel pipe base.		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Gas Meter Shed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR Q & Access at gathering location. Gas Meter Run. Chart in Meter Box dated 12-1-25. Meter Calibration/Test Log dated 11-19-25. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Flowline riser at wellhead with valve and no plug. **Open ended valve missing plug**.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).	Date:	12/29/2025
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. **Open ended line/valve missing plug**. Casing valve open.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).	Date:	12/29/2025

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Location Construction

Location ID: 278475 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment: No COA's.

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 278475 Type: WELL API Number: 125-09327 Status: PR Insp. Status: PR

Producing Well

Comment: Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.
Electronic Well File reflects last Production/Status reported 9/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404469768	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7370859
720900452	Field audit photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7370857